

4-20mA transmitter for PT100, including 3-wire PT.100 sensor, steel and 2M steel Flex cable. Supply voltage 24VDC.

## FEATURES

- Pt.100 transmitter for your mounting
- 2 - 3-wire pt.100 sensor (red to 16, 2 x blue to 18 and A2)
- 24v to 15 and 26
- 4 - 20 mA power Out of 16 and 26
- 4 - 20 mA The output gives power to PLC / instrument
- Including PT100 feel with 80mm, Ø4MM Steel Tips
- 2 meter Flex cable
- Supply voltage: 24VDC
- Dim : H 74 x L 105 x B 22 mm



**SPECIFICATIONS**

|                 |   |   |
|-----------------|---|---|
| Operating Temp. | : | 0 - 50° C                                   |
| Forsyning       | : | 24 VDC 2 W                                  |
| Montering       | : | DIN skinne eller panelmontage               |
| Måleområde      | : | -20 - 130 °C                                |
| Stik            | : | Skrueterminaler                             |
| Udgange         | : | 4-20mA. Strøm ved: -20 °C 4 mA 130 °C 20 mA |

