

Temperature/humidity meter for GUDE NPOWER PDUs, -20 to +80°C, 0-100rH

FEATURES

Temp/humidity meter with RJ45 for GUDE

Up to 40 meters

Temperature: -20°C to +80°C at $\pm 2^\circ\text{C}$ (maximum)
and $\pm 1^\circ\text{C}$ (typical)

Humidity: 0-100% at $\pm 3\%$ (typical) and 10-80% at
 $\pm 2\%$ (typical)

Sensor housing: plastic

Dimensions: 42 x 20 x 35 mm

Weight: 29g

